



PIS

Product Information System

Service Letter Tracking Help

[Home](#) > [Selection Criteria](#)

Serial No/PIN Status

Selected Criteria

Market Org: **NACD**
 Region: **EAST**
 District: **HOUS**
 Dealer: **E310**
 Dealer Desc: **Mustang Machinery/Power Systems**
 Serial/PIN: **SDN00908**

[Selection Criteria](#)

[Dealer Totals](#)

[Program Totals](#)

[Serial No/PIN Status](#)

[Summary](#)

[Summary by Dealer](#)

| Serial/PIN | MFG Model | Assigned Dealer | Last Repair Dealer | Customer | Pgm No | Description | Status | Letter Date | Term Date | Repair Dealer | Repair Date | PD Code | Est. Total Labor Hours |
|------------|-----------|-----------------|--------------------|---------------------|-------------------------|--|--------|-------------|-----------|---------------|-------------|---------|------------------------|
| SDN00908 | C32 | Z800 | L050 | Seabed Geosolutions | PI32648 | Replacing The Oil Pump On Certain C32 Ma | Open | 24Jun2016 | 30Jun2017 | | | | 10.5 |
| | | | | | PS54022 | Replacing Camshaft And Followers On Cert | Open | 26Mar2019 | 31Mar2024 | | | | 30.0 |

[site map](#) | [support](#) | [privacy policy](#)

Caterpillar confidential: **Yellow** © Caterpillar Inc. 2003 All rights reserved. Last Updated: Wed Apr 14 2021 15:17:46 GMT-0500 (Central Daylight Time)